

Anderson County Schools Local Planning Committee Facility Assessments

February 24, 2020







Condition Description

SECTION 202 | PRIORITY LISTINGS

- Priority 1 Educational Projects to begin within the Biennium
- Priority 2 Educational Projects not Scheduled within the Biennium
- **Priority 3** Non-Educational Additions or Expansions
- **Priority 4** Management Support Facilities
- **Priority 5** Discretionary Construction Projects

Priority 1

- Critical Condition Elements
 - Requires immediate replacement / repair within the current fiscal year

< 1 year

- To be considered:
 - past the point of economic repair
 - defective
 - Non-functional

- Poor Condition Elements
 - Requires replacement or major repair action within 1-2 years

1-2 years

 Show aging and are beginning to deteriorate suggesting a replacement soon.

Priority 2

- Fair Condition Elements
 - Operational but may require replacement or major repair action within 3-4 years

Shows adequate aging and operational with no observed or reported issues.

KFICS Architectural Element Definitions

Exterior Elements –

Foundations

· Below grade structure

Superstructure

· Above grade structure

Ext. Walls

· Wall assemblies

Ext. Windows

- Framing type (AL / HM / WD)
- Glazing type (Single / Insulated)

Ext. Doors

- Framing type (AL / HM / Vinyl)
- Door type (AL / HM / WD)
- Hardware type (Panic HDWR / ADA?)

Industrial Doors

Overhead Doors

Roof

- Roofing assemblies
- · Draining system

Interior Elements –

Int. Doors

- Framing type (AL / HM / Vinyl)
- Door type (AL / HM / WD)
- Hardware type (Panic HDWR / ADA?)

Stairs / Ramps

- · Structure / assembly type
- Hardware type (Railings)

Wall Finishes

- Paint
- Ceramic Tiles
- Paneling

Floor Finishes

- Carpet
- VCT / Ceramic / Quarry
- Hardwood

Ceiling Finishes

- Acoustical Tiles
- Gypsum

Kitchen

Equipment

Site Elements -

Roadways

- Paving & Curbs
- Steps / Ramps
- Signage / Painted Markups

Parking

- Paving & Curbs
- Steps / Ramps

Ped Paving

Paving & Curbs

Site Development

- Fencing / Gates
- Playground
- · Canopies (Wall Hung / Independent)
- Retaining Wall

<u>Garbage</u>

- Pad
- · Fencing / Gates



Ezra Sparrow Early Childhood Center



- Constructed: 2012
- Critical Condition Elements (2012)
 - None
- Poor Condition Elements (2012)
 - None
- Fair Condition Elements (2012)
 - None



- Program Deficiencies:
 - None


Total Replacement/Repair Costs: \$0



Emma B Ward Elementary School



- Constructed: 2008
- Critical Condition Elements (2008)
 - None
- Poor Condition Elements (2008)
 - None
- Fair Condition Elements (2008)
 - Domestic Water Heaters \$131,474,
 - Branch Wiring \$155,002



- Program Deficiencies:
 - None

Total Replacement/Repair Costs: \$286,476



Robert B Turner Elementary School



- Constructed: 2002
- Critical Condition Elements (2002)
 - None
- Poor Condition Elements (2002)
 - Domestic Water Heaters \$113,063
 - Branch Wiring \$1,315,418
- Fair Condition Elements (2002)
 - Roofing \$1,680,069



- Program Deficiencies @ \$243.24:
 - (2) Preschool Classrooms @ 825 sf (served by Ezra)
 - *Computer Lab @ 800 sf

*Consider reusing Room 215 which formerly was the Computer Lab but now is the larger Resource Rooms.

- **(2) Resource Rooms @ 400 sf each
- **If 215 is re-designated as Computer Lab, (2) Resources are needed.
- System Replacement/Repair Costs: \$3,108,550
- Program Deficiencies Costs: \$262,962
- Total Replacement/Repair Costs: \$3,371,512



Anderson County Middle School



- Constructed: 1996 / 2007
- Critical Condition Elements (1996)
 - Domestic Water Heaters \$183,075
 - Controls & Instrumentation \$464,424
 - Branch Wiring \$215,841
- Poor Condition Elements (1996)
 - Sanitary Waste \$25,592
 - Primary HVAC Pumps \$3 9,018
 - Packaged AC Units \$1,676,196
 - Lighting Equipment \$459,733
 - Intercomm. & Paging \$102,648

- Clock & Program \$58,828
- Fire Alarms \$88,160
- Security Systems \$151.890
- Exit & Emergency Light \$12,51

- Scole

 O.3517": 22" 5.0938"
- Fair Condition Elements (1996)
 - Roofing \$2,720,735

• (1996) Replacement/Repair Costs: \$6,139,823

Anderson County Middle School



- Constructed: 1996 / 2007
- Critical Condition Elements (2007)
 - None
- Poor Condition Elements (2007)
 - Branch Wiring \$3,233
- Fair Condition Elements (2007)
 - None



- Program Deficiencies @ \$246.09:
 - (1) Standard Classroom @ 750 sf
 - (2) Resource Room @ 375 sf each
 - (3) Computer Classroom @ 900 sf
 - Custodial Receiving @ 250 sf
- Program Deficiencies Costs: \$1, 542,395
- (1996) Replacement/Repair Costs: \$6,139,823
- (2007) Replacement/Repair Costs: \$3,233
- Total Replacement/Repair Costs: \$7,685,451







- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005
- Critical Condition Elements (1965)
 - Exterior Windows \$779,009
 - Interior Doors \$153,116
 - Sanitary Waste \$12,939
 - Branch Wiring \$108,793
 - Sanitary Sewer \$27,620
 - Storm Sewer \$122,867
- Poor Condition Elements (1965)
 - Roofing \$1,372,392
 - Electrical Service / Distrib. \$294,963

- Fair Condition Elements (1965)
 - Exterior Doors \$42,281
 - Roadways \$86,963
 - Parking \$99,927
 - Ped Parking \$52,309
 - Site Development \$55,581
 - Plumbing Fixtures \$629,10
 - Domestic Water Heaters \$142,752
- (1965) Replacement/Repair Costs: \$3,980,613





- Constructed: 1965/ 1979/ 1985/ 1989/ 1991/ 1994/ 1998/ 1999/ 2000/ 2005
- Critical Condition Elements (1979)
 - Branch Wiring \$5,626
 - Sanitary Waste \$669
- Poor Condition Elements (1979)
 - Exterior Windows \$40,285
 - Roofing \$70,791
 - Fittings \$16,065
 - Interior Doors \$7,918
 - Wall Finishes \$27,987
 - Floor Finishes \$48,521
 - Ceiling Finishes \$44,260
 - Electrical Service / Distrib. \$15,253

- Fair Condition Elements (1979)
 - Plumbing Fixtures \$32,533
 - Domestic Water Distr. \$7,382

• (1979) Replacement/Repair Costs: \$317,290





- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005
- Critical Condition Elements (1985)
 - Exterior Windows \$47,611
 - Interior Doors \$9,358
 - Sanitary Waste \$791
 - Branch Wiring \$6,659
- Poor Condition Elements (1985)
 - Fittings \$18,986
 - Wall Finishes \$33,077
 - Floor Finishes \$57,344
 - Ceiling Finishes \$52,309
 - Electrical Service / Distrib. \$18,027

- Fair Condition Elements (1985)
 - Roofing \$41,938
 - Plumbing Fixtures \$38,44
 - Domestic Water Distr. \$8,725
- (1985) Replacement/Repair Costs: \$333,264





- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005
- Critical Condition Elements (1989)
 - Branch Wiring \$6,059
 - Sanitary Waste \$721
- Poor Condition Elements (1989)
 - Exterior Windows \$43,387
 - Roofing \$76,435
 - Fittings \$17,302
 - Interior Doors \$8,528
 - Wall Finishes \$30,142
 - Floor Finishes \$52,257
 - Ceiling Finishes \$47,668
 - Electrical Service / Distrib. \$16,428

- Fair Condition Elements (1989)
 - Plumbing Fixtures \$35,038
 - Domestic Water Distr. \$7,951

• (1989) Replacement/Repair Costs: \$341,916





- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005
- Critical Condition Elements (1991)
 - Branch Wiring \$29,461
 - Sanitary Waste \$3,504
- Poor Condition Elements (1991)
 - Exterior Windows \$210,955
 - Exterior Doors \$11,450
 - Roofing \$371,642
 - Fittings \$84,125
 - Interior Doors \$41,464
 - Wall Finishes \$146,557
 - Floor Finishes \$254,082
 - Ceiling Finishes \$231,773
 - Electrical Service / Distrib. \$79,876

- Fair Condition Elements (1991)
 - Plumbing Fixtures \$170,360
 - Domestic Water Distr. \$38,657

• (1991) Replacement/Repair Costs: \$1,673,906





- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005
- Critical Condition Elements (1994)
 - Branch Wiring \$19,608
 - Sanitary Waste \$2,332
- Poor Condition Elements (1994)
 - Roofing \$247,350
 - Electrical Service / Distrib. \$53,162
- Fair Condition Elements (1994)
 - Exterior Windows \$140,403
 - Plumbing Fixtures \$113,385
 - Domestic Water Distribution \$25,729

• (1994) Replacement/Repair Costs: \$601,969





- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005
- Critical Condition Elements (1998)
 - Branch Wiring \$8,188
- Poor Condition Elements (1998)
 - Roofing \$103,293
 - Electrical Service / Distrib. \$16,428
- Fair Condition Elements (1998)
 - Sanitary Waste \$974

• (1998) Replacement/Repair Costs: \$128,883







- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005
- Critical Condition Elements (1999)
 - Branch Wiring \$6,059
- Poor Condition Elements (1999)
 - Exterior Windows \$40,285
 - Roofing \$76,435
 - Electrical Service / Distrib. \$16,428
- Fair Condition Elements (1999)
 - None

• (1999) Replacement/Repair Costs: \$98,922







- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005
- Critical Condition Elements (2000)
 - Branch Wiring \$2,457
- Poor Condition Elements (2000)
 - Roofing \$30,997
 - Electrical Service / Distrib. \$6,662
- Fair Condition Elements (2000)
 - None

• (2000) Replacement/Repair Costs: \$40,116





- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005
- Critical Condition Elements (2005)
 - Branch Wiring \$62,817
- Poor Condition Elements (2005)
 - None
- Fair Condition Elements (2005)
 - None

(2005) Replacement/Repair Costs: \$62,817

Anderson County High School Annex



- Constructed: 1970 / 1995 / 1998
- Critical Condition Elements (1970)
 - Storm Sewer \$106,793

- Poor Condition Elements (1970)
 - Exterior Window \$33,854
 - Roofing \$1,192,849
 - Interior Doors \$16,430



- Fair Condition Elements (1970)
 - Roadways \$91,192
 - Parking Lots \$104,786
 - Ped Paving \$45,466
 - Site Development \$58,283
 - Domestic Water Distrib. \$80,230
 - Branch Wiring \$94,560
- (1970) Replacement/Repair Costs: \$1,824,443

Anderson County High School Annex



- Constructed: 1970 / 1995 / 1998
- Critical Condition Elements (1995)
 - Roofing \$147,266

- Poor Condition Elements (1995)
 - None



- Fair Condition Elements (1995)
 - Domestic Water Distrib. \$9,905
 - Branch Wiring \$11,674

• (1995) Replacement/Repair Costs: \$168,845



Anderson County High School Annex



- Constructed: 1970 / 1995 / 1998
- Critical Condition Elements (1998)
 - None

- Poor Condition Elements (1998)
 - Roofing \$99,015



- Fair Condition Elements (1998)
 - Domestic Water Distrib. \$6,660
 - Branch Wiring \$7.849

(1998) Replacement/Repair Costs: \$113,524



Anderson County High School/Annex





- Constructed: 1965/1979/1985/1989/1991/1994/1998/1999/2000/2005 + 1970/1995/1998
- Program Deficiencies @ \$254.34:
 - (1) Resource Room @ 375 sf
 - (1) Computer Lab @ 1280 sf

Model program assessment includes High School Annex Building

Program Deficiency Costs: \$619,019

HS Annex:

(1970) Replacement/Repair Costs: \$1,824,443 (1995) Replacement/Repair Costs: \$168,845 (1998) Replacement/Repair Costs: \$113,524 Sub-total Replacement/Repair Costs: \$2,106,812 • High School:

(1965) Replacement/Repair Costs: \$3,980,613

(1979) Replacement/Repair Costs: \$317,290

(1985) Replacement/Repair Costs: \$333,264

(1989) Replacement/Repair Costs: \$341,916

(1991) Replacement/Repair Costs: \$1,673,906

(1994) Replacement/Repair Costs: \$601,969

(1998) Replacement/Repair Costs: \$128,883

(1999) Replacement/Repair Costs: \$98,922

(2000) Replacement/Repair Costs: \$40,116

(2005) Replacement/Repair Costs: \$62,817

Sub-total Replacement/Repair Costs: \$8,198,715

Combined Costs: \$10,305,527

Anderson Co. Bus Garage



- Constructed: 1990
- Critical Condition Elements (1990)
 - Domestic Water Distrib. \$27,476
 - Sanitary Waster \$2,300
 - Compressed Air Systems \$5,660
 - Exhaust Ventilation System \$12,877
 - Unit Air Conditioner \$3,268
 - Electrical Service Distrib. \$21,101

- Branch Wiring \$4,079
- Lighting Equipment \$37,278
- Exit & Emerg. Light Systems \$4,16
- Water Supply \$4,053
- Site Lighting \$1,843

- Fair Condition Elements (1990)
 - Exterior Windows \$12,614 Floor Finishes \$11,727
 - Exterior Doors -- \$5,299Ceiling Finishes \$36,749
 - Industrial Doors \$18,498 Roadways \$7,540
 - Roofing \$104,548
 Parking Lots \$8,664
 - Fittings \$5,273 Ped Paving \$4,535
 - Int. Doors \$29,283
 Site Development \$4,819
 - Wall Finishes \$19,661Garbage \$1,000

- Poor Condition Elements (1990)
 - None

Total Replacement/Repair Costs: \$394,313

Anderson Co. Central Office



- Constructed: 2007
- Critical Condition Elements (2007)
 - None

- Fair Condition Elements (2007)
 Elevators & Lifts -\$2,780
 - Domestic Water Heaters \$34,292
 - Branch Wiring \$40,254

- Poor Condition Elements (2007)
 - None

Total Replacement/Repair Costs: \$77,326

Anderson Co. Maintenance



- Constructed: 2005
- Critical Condition Elements (2005)
 - Compressed Air Systems \$6,966
 - Unit Air Conditioner \$4,022
 - Electric Baseboards Heaters \$5,055
 - Branch Wiring \$5,021
- Poor Condition Elements (2005)
 - None

- Fair Condition Elements (2005)
 - None

Total Replacement/Repair Costs: \$21,064



Questions?

